



TECNOMOTOR

RELEASE 177:

I	Modifiche ai sistemi di Autodiagnosi
GB	Changes to the self-diagnosis systems
E	Cambios en los sistemas diagnóstico



Via Modena 34,
Correggio Italy
Tel +39 0522747411
www.tecnomotor.it

(ITA) Implementata impostazione calibrazione dinamica - TELECAMERA MULTIFUNZIONE
(GB) Implemented dynamic calibration setting - MULTI-FUNCTION CAMERA
(ESP) Configuración de calibración dinámica implementada - CÁMARA MULTIFUNCIÓN

BMW X1 (F48) SDRIVE 20 I (141 kw) (2015-)
BMW X1 (F48) SDRIVE 18 I (103 kw) (2015-)
BMW X1 (F48) SDRIVE 28 I (170 kw) (2015-)
BMW X1 (F48) XDRIVE 20 I (141 kw) (2015-)
BMW X1 (F48) XDRIVE 25 I (170 kw) (2015-)
BMW X1 (F48) SDRIVE 18 I (100 kw) (2015-)
BMW X1 (F48) SDRIVE 18 D (110 kw) (2015-)
BMW X1 (F48) XDRIVE 20 D (140 kw) (2015-)
BMW X1 (F48) SDRIVE 18 D (110 kw) (2015-)
BMW X1 (F48) XDRIVE 25 D (170 kw) (2015-)
BMW X1 (F48) SDRIVE 16 D (85 kw) (2015-)
BMW X1 (F48) SDRIVE 20 D (140 kw) (2015-)
BMW X1 (F48) XDRIVE 18 D (110 kw) (2015-)
BMW X1 (F48) XDRIVE 20 D (140 kw) (2015-)
BMW X1 (F48) SDRIVE 18 D (110 kw) (2015-)
BMW X1 (F48) XDRIVE 20 D (140 kw) (2015-)