

RELEASE 179:

	Modifiche ai sistemi di Autodiagnosi
	Changes to the self-diagnosis systems
	Cambios en los sistemas diagnóstico



Via Modena 34,
Correggio Italy
Tel +39 0522747411
www.tecnomotor.it

(ITA) Implementate nuove impostazioni SERVICE
(GB) Implement new SERVICE settings
(ESP) Implementar nuevas configuraciones de SERVICIO

BMW 1-SERIE (F20) - - - CBS (CAN) (2010-)
 BMW 1-SERIE (F21) - - - CBS (CAN) (2011-)
 BMW 2-SERIE ACTIVE TOURER (F45) - - - CBS (CAN) (2014-)
 BMW 2-SERIE CABRIO (F23) - - - CBS (CAN) (2013-)
 BMW 2-SERIE COUPÉ (F22) - - - CBS (CAN) (2013-)
 BMW 2-SERIE GRAN TOURER (F46) - - - CBS (CAN) (2015-)
 BMW 3-SERIE (F30) - - - CBS (CAN) (2011-)
 BMW 3-SERIE GT (F34) - - - CBS (CAN) (2013-)
 BMW 3-SERIE TOURING (F31) - - - CBS (CAN) (2012-)
 BMW 4-SERIE CABRIO (F33) - - - CBS (CAN) (2013-)
 BMW 4-SERIE COUPÉ (F32) - - - CBS (CAN) (2013-)
 BMW 4-SERIE GRAN COUPÉ (F36) - - - CBS (CAN) (2014-)
 BMW 5-SERIE (F10) - - - CBS (CAN) (2010-)
 BMW 5-SERIE GT (F07) - - - CBS (CAN) (2009-)
 BMW 5-SERIE TOURING (F11) - - - CBS (CAN) (2010-)
 BMW 7-SERIE (F01-F02-F03-F04) - - - CBS (CAN) (2008-2015)
 BMW X1 (F48) - - - CBS (CAN) (2015-)
 BMW X3 (F25) - - - CBS (CAN) (2010-)
 BMW X5 (F15) - - - CBS (CAN) (2013-)
 MINI MINI-F60 COOPER COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 COOPER D COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 COOPER S COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 COOPER SD COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 COOPER SE COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 COOPER WORKS COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 ONE COUNTRYMAN - - - CBS (CAN) (2016-)
 MINI MINI-F60 ONE D COUNTRYMAN - - - CBS (CAN) (2016-)