

技術通報

Product: BMW Diag E Series Software

Part No.: BMW Diag E Series Software

Version: 2017.06

Description: Version update notes

Date: 2017/06/14	From: AUTOLAND SCIENTECH Taiwan	Page: 1/3
-------------------------	--	------------------

Version upgrade to 2017.06

1. Model E81/E82/E87/E88, supplement FRM2 Footwell module 2 system
2. Model E90/E91/E92/E93, supplement FRM2 Footwell module 2 system
3. Model X5-E70, supplement FRM2 Footwell module 2 system
4. Model X6-E71, supplement FRM2 Footwell module 2 system
5. Model E60/E61, DME system, N54 engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
6. Model E60/E61, DME system, N54 engine, MS81 sub version, increase Diagnosis module for tank leakage (USA only) function
7. Model E60/E61, DME system, S85 engine, MSS65 sub version, increase Diagnosis module for tank leakage (USA only) function
8. Model E63/E64, DME system, S85 engine, MSS65 sub version, increase Diagnosis module for tank leakage (USA only) function
9. Model X5-E70, DME system, N52K engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
10. Model X5-E70, engine (DDE) system, M57TU2 TOP (DDE7.3) engine, increase SCR system (USA only), function include SCR activations and adjustments
11. Model X5-E70, FRM2 Footwell module 2 system, increase FRM short circuit reset function
12. Model X6-E71/E72, DME system, N54 engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
13. Model X6-E71/E72, DME system, N54 engine, MS81 sub version, increase Diagnosis module for tank leakage (USA only) function
14. Model X6-E71/E72, DME system, N63 engine, MS85 sub version, increase Diagnosis module for tank leakage (USA only) function
15. Model X6-E71/E72, FRM2 Footwell module 2 system, increase FRM short circuit reset function
16. Model E81/E82/E87/E88, DME system, N51 engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function

Technical Information

技術通報

Product: BMW Diag E Series Software

Part No.: BMW Diag E Series Software

Version: 2017.06

Description: Version update notes

Date: 2017/06/14	From: AUTOLAND SCIENTECH Taiwan	Page: 2/3
-------------------------	--	------------------

17. Model E81/E82/E87/E88, DME system, N52K engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
18. Model E81/E82/E87/E88, DME system, N54 engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
19. Model E81/E82/E87/E88, DME system, N54 engine, MS81 sub version, increase Diagnosis module for tank leakage (USA only) function
20. Model E81/E82/E87/E88, FRM2 Footwell module 2 system, increase FRM short circuit reset function
21. Model E90/E91/E92/E93, DME system, N51 engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
22. Model E90/E91/E92/E93, DME system, N52 engine, MS70 sub version, increase Diagnosis module for tank leakage (USA only) function
23. Model E90/E91/E92/E93, DME system, N52K engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
24. Model E90/E91/E92/E93, DME system, N54 engine, MS80 sub version, increase Diagnosis module for tank leakage (USA only) function
25. Model E90/E91/E92/E93, DME system, N54 engine, MS81 sub version, increase Diagnosis module for tank leakage (USA only) function
26. Model E90/E91/E92/E93, DME system, S65 engine, MSS60 sub version, increase Diagnosis module for tank leakage (USA only) function
27. Model E90/E91/E92/E93, engine (DDE) system, M57TU2 TOP (DDE7.3) engine, increase SCR system (USA only), function include SCR activations and adjustments
28. Model E90/E91/E92/E93, FRM2 Footwell module 2 system, increase FRM short circuit reset function
29. All models, Data Stream, improve displaying problem
30. Model E31/E32/E36/E34/E38/E39/E46/X5-E53/X3-E83/Z3-E36/Z8-E52, improve short test function
31. Model E39/E46/X3-E83/X5-E53/Z4-E85/E86, improve DME-EWS/CAS sync function
32. Model E46, DME system, improve system connection stability

Technical Information

技術通報

Product: BMW Diag E Series Software

Part No.: BMW Diag E Series Software

Version: 2017.06

Description: Version update notes

Date: 2017/06/14	From: AUTOLAND SCIENTECH Taiwan	Page: 3/3
-------------------------	--	------------------

33. Model E63 M6, improve Register battery replacement function