

RELEASE 178:

	Modifiche ai sistemi di Autodiagnosi
	Changes to the self-diagnosis systems
	Cambios en los sistemas diagnóstico



Via Modena 34,
Correggio Italy
Tel +39 0522747411
www.tecnomotor.it

(ITA) Migliorata gestione AZZERAMENTO SERVICE
(GB) Improved Management SERVICE RESET
(ESP) Gestión mejorada RESET DE SERVICIO

ALFA ROMEO SPIDER (939E) - - - AUTOMATIC PROCED (CAN) (2006-2010)
FIAT CROMA (194A) - - - AUTOMATIC PROCED (CAN) (2005-2010)

(ITA) Migliorata gestione AZZERAMENTO SERVICE
(GB) Improved Management SERVICE RESET
(ESP) Gestión mejorada RESET DE SERVICIO

DACIA DUSTER (HS) 13 - - - INSTRUMENT (CAN) (2010-)
DACIA LODGY (JS) - - - INSTRUMENT (CAN) (2010-)
DACIA SANDERO (5S) - - - INSTRUMENT (CAN) (2012-)
RENAULT CLIO (III BR-CR) - - - INSTRUMENT (CAN) (2005-2012)
RENAULT CLIO GRANDTOUR (III KR0-1) - - - INSTRUMENT (CAN) (2007-2012)
RENAULT CLIO VAN (III BR-CR) - - - INSTRUMENT (CAN) (2005-2012)
RENAULT THALIA (II LU) - - - INSTRUMENT (CAN) (2008-)

(ITA) Migliorati testi reset SERVICE
(GB) Improved SERVICE reset texts
(ESP) Textos mejorados Restablecimiento de SERVICIO

FORD KUGA (MY2012) - - - MANUAL PROCED. - - - (2012-)
FORD KUGA VAN (MY2012) - - - MANUAL PROCED. - - - (2014-)